

VI. Documentation from a trained professional (i.e., a person certified by the American Backflow Prevention Association, an inspector from a state or local governmental agency who has experience and/or training in backflow prevention, or a consultant with such experience and/or training) that there are no cross-connections that would allow the backflow of wastewater into a water supply well, irrigation well, or surface water as identified on the Site Map required in I.F above.

From Table 1 in the General Order (pages 26-29)

July 1, 2008	Identification of Backflow Problems	Identify backflow problems with proposed remediation and schedule.	Trained Professional**
July 1, 2009	Item VI	Documentation there are no cross connections.	Trained Professional**

** A trained professional could be a person certified by the American Backflow Prevention Association, an inspector for a state or local governmental agency who has experience and/or training in backflow prevention, or a consultant with such experience and/or training.